

DEPARTMENT OF THE ARMY TECHNICAL MANUAL

DIRECT SUPPORT AND GENERAL SUPPORT MAINTENANCE REPAIR
PARTS AND SPECIAL TOOLS LIST
FOR
SIGNAL GENERATOR
HEWLETT-PACKARD MODEL 205AG
(NSN 6625-00-643-1568)
Current as of 11 September 1974

Headquarters, Department of the Army, Washington, D.C.
18 December 1974

Section	I.	INTRODUCTION		Paragraph	Page
		Scope		1	1
		General		2	1
		Explanation of columns		3	1
		How to locate repair parts.....		4	2
		Recommendation for maintenance publications improvements		5	2
	II.	REPAIR PARTS LIST			
		FUNCTIONAL			
		GROUP	GROUP TITLE	MODEL No.	PART No.
		5170	Generator Signal	205AG	8616377
	III.	FEDERAL STOCK NUMBER, REFERENCE INDEX			

SECTION I
INTRODUCTION

1. Scope

This manual lists repair parts that are required for maintenance of Signal Generator, Hewlett-Packard Model 205AG and is applicable to Army Area Calibration Laboratories (ACCL's) and Army Area Calibration Teams (ACCT's).

NOTE

Throughout this manual, DS is used to indicate AACT, and GS is used to indicate AACL.

2. General

This manual is divided as follows:

a. Section I. Introduction.

b. Section II. Repair Parts List. A list, in alphabetical sequence, of repair parts authorized for the performance of maintenance at the AACT and AACL support levels.

c. Section III. Federal Stock Number and Reference Number Index. A list in ascending numerical sequence, of all Federal stock numbers (FSN's) appearing in the repair parts list, followed by a list of all reference numbers in alpha-numeric sequence appearing in the list. The FSN's and reference numbers are cross-referenced to a figure number and item number in column 10.

NOTE

The figure and item number columns represent cross-reference numbers, since illustrations are not included in this manual.

3. Explanation of Columns

Refer to Section I of TM 9-4931-700-34P for explanation of columns (para 3), special information (para 4, except for subparagraph 40 which is not applicable to this manual), and abbreviations (para 6).

4. How to Locate Repair Parts

When FSN or reference number is unknown, use the repair parts listing and locate the item by description.

When Federal stock number or reference number is known, use the list of FSN's or the reference numbers and locate the cross-referenced figure and item number. Locate the cross-referenced figure and item number under column 10 of the repair parts list for the complete description of the repair parts.

5. Recommendation for Maintenance Publications Improvements

You can improve this manual by recommending improvements using DA Form 2028 (Recommended Changes to Publications and Blank Forms) and mailing the form to Commander, US Army Missile Command, ATTN: AMSMI-MFM, Redstone Arsenal, AL 35809. A reply will be furnished direct to you.